

Work Order ID 62988

Friday, October 15, 2010 9:22:39 AM



Page 1

Item ID:	D2235-1	Accept		Setup	Start	
Revision ID:					Stop	
Item Name:	Basket Rib					
Start Date:	10/15/2010	Start Qty:	10.00			
Required Date:	10/21/2010	Req'd Qty:	10.00			
Reference:						

Approvals:	Process Plan:		Date:	10/10/15	Tooling:		Date:		Run	Start	
	QC:		Date:		SPC (Y/N):		Date:			Stop	

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr								
D2235	Rev B1								

100		0.00							
	Large Fab								
Large Fab	Memo	0.00							
Large Fab	1- Pick D3166-1 and cut as per dwg D2235 using DT8302 2- remove identification markings on tube 3- deburr								

SAD 10-10-20

110	QC5- Inspect part completeness to step on W/O	0.00							
QC	Memo	0.00							
Quality Control									

10

10-10-20

120	Identify as per dwg & Stock Location: WA	0.00							
Packaging	Memo	0.00							
Packaging									

SAD

10

10-10-20

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 62988

Friday, October 15, 2010 9:22:39 AM

Page 2

Item ID: D2235-1

Accept

Setup Start

Revision ID:

Stop

Item Name: Basket Rib

Start Date: 10/15/2010 Start Qty: 10.00

Cust Item ID:

Required Date: 10/21/2010 Req'd Qty: 10.00

Customer:

Reference:

Approvals:

Process Plan: _____

Date: _____

Tooling: _____

Date: _____

Run Start

QC: _____

Date: _____

SPC (Y/N): _____

Date: _____

Stop

Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

130

QC21- Final Inspection - Work Order Release

0.00



QC

Memo

0.00

Quality Control

10/10/20 [Signature]
MF
10-10-20

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Friday, October 15, 2010 9:22:44 AM

Page 1

Work Order ID: 62988



Parent Item: D2235-1



Parent Item Name: Basket Rib

Start Date: 10/15/2010

Required Date: 10/21/2010

Start Qty: 10.00

Required Qty: 10.00

Comments: IPP Rev:A New Issue 08-12-01 DD verified by:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	-------------	--------------	---------------	----------------	--------

D3166-1		Manufactured	No			100	Each	11.0000	1	10			
---------	--	--------------	----	--	--	-----	------	---------	---	----	--	--	--



Basket Hoop

SAN 10-10-20

Location

Loc Qty

Loc Code

WA

11

62472

11

10

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____


NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries



DESIGN B WILLIAMS	DRAWN BY B WILLIAMS	DART AEROSPACE LTD VICTORIA INTERNATIONAL AIRPORT, CANADA	
CHECKED <i>BW</i>	APPROVED <i>BW</i>	DRAWING NO. D2235	REV. B SHEET 1 OF 1
DATE 94:12:16		TITLE BASKET RIBS	
BI 02.03.06 <i>U-#</i>		CAN BE MADE FROM D3166-1	


RELEASED
R 960507



D2235-1

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO A REVIEW
WITH THE
WORK ORDER
NO. *62988*

B/10-10-15



D2235-3

CAN BE MADE FROM D3166-1 *BI*
MATERIAL: 304/316 SS, 3/4 X 3/4 X 0.063 WALL SQR.

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries